

### BAKER STREET HOME INSPECTION SERVICES INC.

3230 Yonge Street, Suite 1717

Toronto, Ontario M4N 3P6

Telephone: 416-483-3535 Fax: 416-483-9756

Website: www.bakerstreet-hi.ca

Email: info@bakerstreet-hi.ca

### HOME INSPECTION REPORT



## Property Address: 308B Hounslow Avenue Date of inspection: April 17, 2024

### **Prepared By:**

Jeff Clarke, CET, RHI

#### BAKER STREET HOME INSPECTION SERVICES INC. 3230 Yonge St, Suite 1717 Toronto, Ontario M4N 3P6 P: 416-483-3535 E: info@bakerstreet-hi.ca

W: www.bakerstreet-hi.ca

**Over 50,000 Inspections Performed Since 1985** 

Residential Property Inspections Commercial Property Inspections Income Property Inspections Inspections of Newly Constructed Homes



# BAKER STREET HOME INSPECTION SERVICES INC.

3335 Yonge Street, Suite 402 Toronto, Ontario M4N 2M1 Telephone: 416-483-3535 Fax: 416-483-9756 Website: www.bakerstreet-hi.ca Email: info@bakerstreet-hi.ca

### **Attention: Prospective Purchasers**

This report has been prepared for the seller to provide them with a better understanding of the condition of their house. The seller has accepted this report as an accurate assessment of the functional condition of their property at the time of the inspection. The report represents our observed opinions.

Baker Street Home Inspection Services Inc. will remain available over the telephone to any interested party to answer questions regarding this property. The reader is cautioned that the report will not convey all information that a prospective buyer may deem relevant. As such, all interested buyers are advised to have their own inspection.

Should any party require further information, Baker Street Home Inspection Services Inc. will provide a 1½ hour on-site orientation of the house for a fee of \$325.00 + HST. Please be advised that Baker Street Home Inspection Services Inc. remains available to all their clients, indefinitely, to address any concerns or questions.

Should you wish clarification, please do not hesitate to contact our office.

Sincerely,

# BAKER STREET HOME INSPECTION SERVICES INC.

BAKERSTREETHOMEINSPEC	CTIONSERVICESINC.					
3230 Yonge Street Suite 1717	Toronto Ontario M4	N 3P6				
Telephone: 416-483-3535	Fax: 416-483-9756	Website: ww	ww.bakerstreet-	hi.ca	Email: inf	o@bakerstreet-hi.ca
PRE-LIST SUMMARY						
Address: 308B Hounslow Avenue	Municipali	ty: Toronto	<ul> <li>Inspection Data</li> </ul>	ate: April 17, 20	24	
General Information:				Inspector:	Jeff Clarke, CET	, RHI 💌
Age of House 20	years. Construction Type:	2 storey 🔻 d	letached	▼ stucco/EIFS		-
This house is in above average	▼ functional condition	on in comparison to	other similar ag	e and size home	s in the neighbou	rhood.
On average; a house of similar age/	size and quality will cost you	ı \$4500-\$5500 <b>-</b>	for annual gen	eral repairs and	on-going mainter	nance.
You will require \$12,000+	(mir	nimum) to address	the functional co	ncerns listed in t	he the report ove	er the next $0-2$ $\checkmark$
MAJOR SYSTEMS - GENERAL	DESCRIPTION AND CO	NDITIONS:				
Roofing systems: asphalt shingles	Secondary roofing s	system:	<b>T</b>	•		
Exterior wall systems: stone venee	er (front) 💌 Second	ary wall siding: st	ucco/EIFS	-		<b>T</b>
Windows(general): Vinyl casemen	it windows	-				
Electrical Systems						
Main service size 200 💌 amp c	ircuit breakers	<ul> <li>Predominant b</li> </ul>	ranch wiring: ro	mex/copper		<b>T</b>
Heating System						
Fuel type: natural gas 🔻 Age of	central heating appliance: 3		years System ty	pe: high-efficie	ncy forced air fu	rnace 💌
Cooling System	I					
System type: central A/C-low velo	city	cooling equipment:	19	years App	rox. tons: 2.5 to	ns 🔻
Plumbing System						
Main supply: 3/4 inch copper line	▼ Predomin	ant water lines PE	X		-	
Interior (general): good overall fun	ctional condition		<b>T</b>			
HOMEOWNER INSURANCE C						
✓ None Identified	<b>_</b>			-		
REQUIRED REPAIRS/MAJOR			_			
Miscellaneous future exterior repai			Time frame		Budget \$ 3,00	
Miscellaneous future interior repair	rs & maintenance		Time frame		Budget \$ 4,00	
A/C is approaching end of expected	d lifespan-budget for replace	ment	<ul> <li>Time frame</li> </ul>	0-2 🔻 years	Budget \$ 5,00	0+
			<ul> <li>Time frame</li> </ul>	vears	Budget \$	
			Time frame	vears	Budget \$	
			▼ Time frame	vears	Budget \$	
			Time frame		Budget \$	
			Time frame		Budget \$	
			Time frame	years	Budget \$	
OTHER RECOMMENDATION	<b>S</b>					
				•		
				•		
				•		
ADDITIONAL INFORMATION	REQUIRED					
ADDITIONAL INFORMATION		ace installation (if a	applicable).		•	
		ace installation (if a	applicable).		<ul><li>▼</li><li>▼</li></ul>	

#### SUMMARY

This report should not be considered as a complete home and property inspection. The Baker Street report is prepared for the owner to provide general information about this property. The inspector is available by telephone to any interested party to answer questions about the house. Please read the full report prior to calling the inspector. We are also available to provide any prospective buyer general orientation, helpful maintenance tips and improvement consulting for a fee of \$325.00 + HST. This general review inspection is essential to compare your expectations, intended use and special needs with the realities of the house. Interested parties should be advised that without this general review our obligation and liability can only remain with the seller.